**SuperSpeed USB 3.0 PCIe Adapter**
(ENLUH-302)

Quick Installation Guide

SuperSpeed USB 3.0 PCIe Adapter
Quick Installation Guide

10/04/V1.0

## For Windows XP/ Windows Vista/ Windows 7

**Notice :** You will need to install the driver for your SuperSpeed USB 3.0 PCIe adapter first. Please follow the procedures as below.

■ **To Install the Driver**

1. Insert the provided CD into your disc drive. Click **autorun.exe** then choose correct product model.
2. Click the **"Driver Setup"** on display screen shot, then click **Next** to continue.
3. After reading **End-User License Agreement,** please choose **"I accept the terms in the License Agreement"** and click **Next.**
4. Please click Browse to choose the Destination Folder. After that, please click **Next.**
5. Click **Install** to install NEC Electronics USB 3.0 Host Controller Driver.
6. It will take a while to install the Driver. The **Software Installation/ Windows Security** may pop-up during installation. Please click **Continue Anyway** to complete the installation.
7. Please click **Finish** to complete the NEC Electronics USB 3.0 Host Controller Driver.

■ **Hardware Installation**

1. Turn off your computer, unplug the power cord from your computer, and then remove the cover of the computer.
2. Plug the PCIe adapter into the PCIe slot of your computer.
3. Plug the power connector from your computer's internal power supply to the SuperSpeed 3.0 PCIe adapter.
4. Put the cover back, plug the power cord back to your computer, and then turn on your computer.

■ **For Window XP :**

You may need to complete the installation of Found New Hardware Wizard under Windows XP system after plugging the SuperSpeed USB 3.0 PCIe adapter.

This Quick Installation Guide describes only the basic instructions on installation. For more information, please refer to the User's Manual on the provided CD-ROM.